PROCEDURE FOR THE CALIBRATION OF THE MARSHALL AUTOMATIC HAMMER TO THE HAND HAMMER AASHTO T 245

A. PURPOSE

This method is intended to provide instruction for the calibration of mechanically operated hammers to yield results comparable to that of the hand operated hammer as specified in AASHTO T 245, Section 2.3. The average actual density obtained using a mechanical hammer is compared to the average actual density obtained using a hand hammer. The number of blows with the mechanical hammer is adjusted accordingly. The hammers are calibrated from 50 to 75 blows per face.

B. PROCEDURE Calibrating the mechanical hammer.

1. Prepare 28 specimens of "E" mix with an identical mixture and compact them in accordance with the following schedule per AASHTO T 245.

No. of Specimens	No. of blows per face	Type Hammer	% AC
5	50	Hand	50 BL OPT
5	75	Hand	75 BL OPT
3	50	Mechanical	50 BL OPT
3	60	Mechanical	50 BL OPT
3	70	Mechanical	50 BL OPT
3	70	Mechanical	75 BL OPT
3	80	Mechanical	75 BL OPT
3	90	Mechanical	75 BL OPT

COMPACTION SCHEDULE

- 2. Calculate the average actual density for each set of specimens for both the hand-held and the mechanical hammers in accordance with GDT-39, "Method of Test for Specific Gravity of Compressed Bituminous Mixtures."
- 3 Plot the density versus the number of blows for the mechanized hammers. Draw a "best-fit" curve through the mechanical hammer data points, creating a separate curve for both the 50 blow and 75 blow data. Draw a straight line across the graph at the point representing the average hand-held hammer density.

C. ADJUSTMENTS FOR THE MECHANICAL HAMMER

The point at which the hand hammer average and the "best-fit" curve for each of the mechanical hammer results intersect will identify the number of blows required using the mechanical hammer to yield either 50 or 75 blow hand hammer results.

D. TOLERANCE

The number of blows is adjusted so as to produce the same compaction produced by the hand hammer.

5-94 Rev. 01 4-98

EQUIPMENT CALIBRATION RECORD

Location (Lab): Calibration Frequency: Next Due Date: Hand Hamme Weight	12 months
Next Due Date: Hand Hamme Weight	
Weight	
Weight	r
_	
_	
_	
Average Density	
Blows	
	
	Avg. Density
Blows	
	Avg. Density
	a marah an af hlassa
Follow instructions to determine correct number blows.	
	aper to plot density versu

5-94